

### Journey of an Instrument NSF

Hans Ashlock hans.ashlock@asp-support.com Lin Yang lin.yang@asp-support.com Steve Gonet steve.gonet@teradyne.com






TERADYNE USERS GRUUA



# Introduction

- Alliance Support Partners, Inc. (ASP)
  - Located in Northern California
  - A proud member of Teradyne Support Network since 2004
  - Delivered over 200 TPS on S9 platform since then
- The Project
  - Rehost from L200 to S9 Platform using TPSCS
  - Two NSFs Timer Counter (TIMEMS) and IEEE
  - 5 New Non-Standard Instruments
    - VM2164 Timer Counter
    - Amrel DC Power Supply (IEEE)
    - Behlman AC Power Supply (IEEE)
    - NI Synchro / Resolver (IEEE)






Using the Timer Counter NSF to take a closer look at how to create and test an NSF in Converter Studio

# **NSF - THE CREATION**




#### **Converter Studio Process**




# Instrument Interchangeability

- Allows instrument interchangeability without changing L200 TPS code
- Instrument NSF
  - Maintains Traceability
  - Reduces Complexity of Re-hosting



# **NSF Architecture in Converter Studio**



# **Timer Counter NSF**

"Customer needs to utilize the L200 PRECOUNT keywords and instrument capability which is not supported by standard S9000 configuration."

#### Agilent E1420

- 200 MHz Frequency
- 9-digit Resolution
- 2 ns (200 ps w/ averaging)



#### VTI VM2164

- 200 MHz Frequency
- 9-digit Resolution
- 1 nS (100 ps w/ averaging)
- 200 Readings per Second
- Arm Delay (PRECOUNT)



# Writing Counter Timer NSF

- SET TIMEMS
  - Configures the Timer Counter Instrument
- READ TIMEMS
  - Reads the Timer Counter Measurement
- PRECOUNT
  - Option in SET TIMEMS
  - Provides delay after Counter Arm Condition



## **Integrate Into Converter Studio**


S VERTER STUDIO	Setup: Build NSF Project
	DIRECTORIES, FILES, OPTIONS SELECTION
PROJECT ADE TYPE	C VC++ Project (VC++ 6.0) CVI Project (VC++ 7.0) CVI Project
SOURCE CODE DIRECTO	C:\FODMS\TPS-S9000\19760-501_JI\Identify_Implemen
Source Files	C Source Files Header Files   CShellANALOG_HW.c CShellNew.def   CShellIEE.c CShellNew.h   CShellNewError.c CShellNewError.h   CShellNewError.c CShellNewGlobals.h   CShellNewUtil.c CShellNewOutput.h   Version.h Version.h
BUILD OPTION	Release Mode Debug Mode
PROJECT LOCATION	C:\FODMS\TPS-S9000\19760-501_JI\Build\Build_NSF_Project Browse
PROJECT NAME	NSF_JI
	NSF BUILD FOLDERS SELECTION (
	ADDITIONAL FOLDERS AND FILES SELECTION (
ADDITIONAL INCLUDE DIRECTORIES	\USR_Vtvm2164 Browse
ADDITIONAL LINKED LIBRARIES	\USR_Vtvm2164\USR_Vtvm2164.lib Browse
ADDITIONAL SOURCE FILES	Browse
0	K Cancel Apply Print Help

# **Testing and Debugging NSF**

NI Spy Capture

TELEVILLE USERS

- Verifies high level calls generate correct low level instrument commands
- Simultaneous Scope on Timer Counter Inputs
  - Verifies correct signal input
- L200 Test Bench
  - Written entirely in L200 Code
  - Use M9 and SCPM
  - No test fixture required





#### **Reflections on Development Process**

- Implementing NSF in DLL was very helpful
  - Debugging
  - Updating NSF w/o reconverting project
- Using existing NSF as template not efficient
  - Differences between old and new instrument
  - Traceability not as important as expected
- Test bench written in L200 has advantages
  - Verifies Custom Code
  - Verifies Pre / Post Code
  - Verifies the way in which functions are called





Resolving issues that arise integrating NSF and new instruments Into customer application.

# **NSF – SPEED BUMPS**



## **Real World Issues**

- Now that the NSF is written and "working" how does it fare when we run the converted TPS?
- Issues Encountered with Timer Counter
  - Order of Operations Issue
  - Counter Overflow Issue
  - Precount Issue
  - Signal Quality Issue

# **Order of Operations Issue**

- **Problem**: Instrument unexpectedly looses configuration
- Root Cause: Order of commands sent to instrument
- Solution: Send commands in correct order
- Complicating Issues:

TELEVILE USERS

- Misunderstanding of documentation
- No feedback from instrument



### **Overflow Issue**

- Problem: measurements periodically return incorrect results
- Root Cause: Instrument HW Bug
- Solution: Fix in SW by initializing twice
- Complicating Factors
  - Occurs infrequently
  - No test case that covered this scenario

# **PRECOUNT** Issue

- Problem: TIMEMS measurements using the PRECOUNT option returning unstable results
- **Root Cause**: Instrument not meeting spec
- Solution: Vendor to ECO instrument
- Complicating Factors

TELEVITE USERS

- No test case to verify instrument meeting spec
- Difficult to verify instrument configured properly

# Signal Integrity Issue


- **Problem**: Readings fail and vary across systems
- Root Cause: Impedance mismatching causes signal reflection though SCPM
  - L200 has a digital switch matrix
  - S9000 has an analog switch matrix
- Complicating Issues:
  - Requires external signal analysis w/ Scope
  - Trial and error

TELEVITE USERS

# Signal Integrity Solution - 50Ω Input

- NSF Keyword: "SOURCE EXT50"
- Use  $50\Omega$  Input Impedance on Counter Timer
- Cleans Up Signal, But Loads it Down

#### Without 50 Ohm Input Impedance





#### With 50Ohm Input Impedance



# **Ideal Solution – Signal Buffer**


- Custom Buffering in Fixture OR
- Off the Shelf Signal Buffer Matrix

#### With ASP Analog Signal Buffer (SBX36)



**Original Signal (No Buffering)** 

SBX36





### **IEEE NSF**

- Amrel DC Power Supply
  - Negative Voltage Programming Issue
  - SLOW Ramp Up Issue
  - No Response Issue
- NAI Synchro-Resolver
  - Instrument Not Functioning





# **Enhance Existing NSF**

- Add on to existing NSFs for debugging
- For example:
  - Enhance SET JUMPER to include debug print of TxConnections

THE SPEC LIMITS ARE: -10	0.00000 TO	100.00000 MICROAMPS	~
Disconnecting Jumper 1 0			
)isconnecting Jumper 2 0			
Connecting Jumper 1 0 - Pin /	A6 to /LOAD2_2	(/19790-501_DCO/Configuration/VXI	I Test Syste
Connecting Jumper 2 0 - Pin /	LOAD2_1 to $/\overline{C7}$	(/19790-501_DCO/Configuration/VXI	I Test Syste
)isconnecting Jumper 1 0			
)isconnecting Jumper 2 0			
PAR 3.4.11: BITE TEST			
PASSED FTS PAR 3.4.11.1:			
PIN P1-A73 IS IN LOGIC	HI STATE		
JIMITS ARE FROM 2.5 VOLTS TO	5.25 VOLTS		



"Some people will never learn anything because they understand everything too soon."

Alexander Pope (1688 - 1744)

To that extent, we certainly learned a lot from this project.

# **NSF – LOOKING BACK**





### **Lessons Learned**

- Writing a good Instrument NSF is a lot of work!
  - Requires a lot of coding and attention to details
  - Requires developing rigorous test cases
  - Requires significant amount of hardware integration work
- Hardware may not behave the same even if it is claimed to be compatible
- Hardware may not work per its datasheet
- Analog Switching is a big problem for signal quality



Q & A

